


Pressure sensors SPAW with display

Peripherals overview

FESTO



Mounting components and accessories		
	Brief description	→ Page/Internet
1	NEBU-M12 Connecting cable	12
2	PQ-RK-22-B Pipe clamp, only for G $\frac{1}{4}$ with internal thread	12
3	QS- $\frac{1}{4}$ Push-in fitting, only for G $\frac{1}{4}$ with internal thread	12